

Getinge Assured

Bowie-Dick Test Card 134°C Interpretation Guide

Unexposed



Fail



Any residual purple colour indicates a fail.

Fail



Any residual purple colour indicates a fail.

Pass



Complete colour change from purple to green, indicates that an effective steam sterilization cycle has been achieved.

Pass



Indication of wet steam but still effective for steam sterilization.

Pass



Indication of dry steam or extended drying time but effective for steam sterilization.